Civil Engineering Database Subject Heading Index

The **Civil Engineering Database (CEDB)** is designed to provide free, easy bibliographic access to all ASCE publications. The database covers ASCE documents published since 1970. It provides access to all the journals, conference proceedings, books, standards, manuals, magazines, and newspapers. The index terms below were assigned to papers published in this journal during 2004 from a CEDB subject heading list. The CEDB and subject heading list can be accessed on the Web at *http://www.pubs.asce.org/cedbsrch.html*.

Absorption
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Asphalt mixes
Investigation of Permeability on Indiana SR-38. — John E. Haddock and Michael Prather; 18(3), 136-41 (2004).

Asphalt pavements
Investigation of Permeability on Indiana SR-38. — John E. Haddock and Michael Prather; 18(3), 136-41 (2004).

Beams
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).

Blast effects
Survey of Window Retrofit Solutions for Blast Mitigation. — Lorraine H. Lin, Eve Hinman, Hollice F. Stone, and Allison M. Roberts; 18(2), 86-94 (2004).
Performance Simulation of Nuclear Containments for Security. — Y. L. Mo; 18(2), 107-15 (2004).

Blasting
Lessons Learned on Improving Resistance of Buildings to Terrorist Attacks. — W. Gene Corley; 18(2), 68-78 (2004).

Boston
Collapse of 2000 Commonwealth Avenue: Punching Shear Case Study. — Suzanne King and Norbert J. Delatte; 18(1), 54-61 (2004).

Bridge decks
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).
Nondestructive Assessment of Damage in Concrete Bridge Decks. — Sarah L. Gassman and Waleed F. Tawhed; 18(4), 220-31 (2004).

Bridge design
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).

Bridge maintenance
Budget Allocation for Steel Bridge Paint Maintenance. — Tarek M. Zayed; 18(1), 36-46 (2004).

Bridge tests
Nondestructive Evaluation of the I-40 Bridge over the Rio Grande River. — David V. Jáuregui and Paul J. Barr; 18(4), 195-204 (2004).

Bridges
Laser-Based Instrumentation for Bridge Load Testing. — P. A. Fuchs, G. A. Washer, S. B. Chase, and M. Moore; 18(4), 213-9 (2004).

Bridges, concrete
Contribution of Intermediate Diaphragms in Enhancing Precast Bridge Girder Performance. — Tanya Green, Nur Yazdani, and Lisa Spainhour; 18(3), 142-6 (2004).

Bridges, girder
Contribution of Intermediate Diaphragms in Enhancing Precast Bridge Girder Performance. — Tanya Green, Nur Yazdani, and Lisa Spainhour; 18(3), 142-6 (2004).

Bridges, highway
Seismic Effect on Highway Bridges in Chi Chi Earthquake. — Yao T. Hsu and Chung C. Fu; 18(1), 47-53 (2004).

Bridges, steel
Budget Allocation for Steel Bridge Paint Maintenance. — Tarek M. Zayed; 18(1), 36-46 (2004).

Bridges, viaduct
Condition Assessment of the Eastbound 6th Avenue Viaduct Using Strain Gauges. — Benjamin J. Allen and Kevin L. Rens; 18(4), 205-12 (2004).

Buckling
Retrofitting a Missouri Steel Baghouse. — Donald D. Liou; 18(3), 159-64 (2004).

Budgets
Budget Allocation for Steel Bridge Paint Maintenance. — Tarek M. Zayed; 18(1), 36-46 (2004).

Building frames
Retrofitting a Missouri Steel Baghouse. — Donald D. Liou; 18(3), 159-64 (2004).

Buildings, multistory
Human Error and Reliability of Multistory Reinforced-Concrete Building Construction. — Deepthi C. Epaarachchi and Mark G. Stewart; 18(1), 12-20 (2004).

Buildings, residential
Collapse of 2000 Commonwealth Avenue: Punching Shear Case Study. — Suzanne King and Norbert J. Delatte; 18(1), 54-61 (2004).

Case reports
Collapse of 2000 Commonwealth Avenue: Punching Shear Case Study. — Suzanne King and Norbert J. Delatte; 18(1), 54-61 (2004).

Chile
Performance and Seismic Vulnerability of Masonry Housing Types Used in Chile. — M. O. Moroni, M. Astroza, and C. Acevedo; 18(3), 173-9 (2004).

Chlorides
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Collapse
Collapse of 2000 Commonwealth Avenue: Punching Shear Case Study. — Suzanne King and Norbert J. Delatte; 18(1), 54-61 (2004).
Lessons Learned on Improving Resistance of Buildings to Terrorist Attacks. — W. Gene Corley; 18(2), 68-78 (2004).
Progressive Analysis Procedure for Progressive Collapse. — S. M. Marjanishvili; 18(2), 79-85 (2004).

Colorado
Condition Assessment of the Eastbound 6th Avenue Viaduct Using Strain Gauges. — Benjamin J. Allen and Kevin L. Rens; 18(4), 205-12 (2004).

Composite materials
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).

Compressive strength
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Concrete deterioration
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Concrete pavements
Assessment of Retrofit Dowel Benefits in Cracked Portland Cement Concrete Pavements. — Jacob E. Hiller and Neeraj Buch; 18(1), 29-35 (2004).

Concrete slabs
Nondestructive Assessment of Damage in Concrete Bridge Decks. — Sarah L. Gassman and Waleed F. Tawhed; 18(4), 220-31 (2004).

Concrete, reinforced
Human Error and Reliability of Multistory Reinforced-Concrete Building Construction. — Deepthi C. Epaarachchi and Mark G. Stewart; 18(1), 12-20 (2004).

Constitutive models
Performance Simulation of Nuclear Containments for Security. — Y. L. Mo; 18(2), 107-15 (2004).

Construction
Human Error and Reliability of Multistory Reinforced-Concrete Building Construction. — Deepthi C. Epaarachchi and Mark G. Stewart; 18(1), 12-20 (2004).

Civil Engineering Database Subject Heading Index

The **Civil Engineering Database (CEDB)** is designed to provide free, easy bibliographic access to all ASCE publications. The database covers ASCE documents published since 1970. It provides access to all the journals, conference proceedings, books, standards, manuals, magazines, and newspapers. The index terms below were assigned to papers published in this journal during 2004 from a CEDB subject heading list. The CEDB and subject heading list can be accessed on the Web at *http://www.pubs.asce.org/cedbsrch.html*.

Absorption
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Asphalt mixes
Investigation of Permeability on Indiana SR-38. — John E. Haddock and Michael Prather; 18(3), 136-41 (2004).

Asphalt pavements
Investigation of Permeability on Indiana SR-38. — John E. Haddock and Michael Prather; 18(3), 136-41 (2004).

Beams
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).

Blast effects
Survey of Window Retrofit Solutions for Blast Mitigation. — Lorraine H. Lin, Eve Hinman, Hollice F. Stone, and Allison M. Roberts; 18(2), 86-94 (2004).
Performance Simulation of Nuclear Containments for Security. — Y. L. Mo; 18(2), 107-15 (2004).

Blasting
Lessons Learned on Improving Resistance of Buildings to Terrorist Attacks. — W. Gene Corley; 18(2), 68-78 (2004).

Boston
Collapse of 2000 Commonwealth Avenue: Punching Shear Case Study. — Suzanne King and Norbert J. Delatte; 18(1), 54-61 (2004).

Bridge decks
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).
Nondestructive Assessment of Damage in Concrete Bridge Decks. — Sarah L. Gassman and Waleed F. Tawhed; 18(4), 220-31 (2004).

Bridge design
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).

Bridge maintenance
Budget Allocation for Steel Bridge Paint Maintenance. — Tarek M. Zayed; 18(1), 36-46 (2004).

Bridge tests
Nondestructive Evaluation of the I-40 Bridge over the Rio Grande River. — David V. Jáuregui and Paul J. Barr; 18(4), 195-204 (2004).

Bridges
Laser-Based Instrumentation for Bridge Load Testing. — P. A. Fuchs, G. A. Washer, S. B. Chase, and M. Moore; 18(4), 213-9 (2004).

Bridges, concrete
Contribution of Intermediate Diaphragms in Enhancing Precast Bridge Girder Performance. — Tanya Green, Nur Yazdani, and Lisa Spainhour; 18(3), 142-6 (2004).

Bridges, girder
Contribution of Intermediate Diaphragms in Enhancing Precast Bridge Girder Performance. — Tanya Green, Nur Yazdani, and Lisa Spainhour; 18(3), 142-6 (2004).

Bridges, highway
Seismic Effect on Highway Bridges in Chi Chi Earthquake. — Yao T. Hsu and Chung C. Fu; 18(1), 47-53 (2004).

Bridges, steel
Budget Allocation for Steel Bridge Paint Maintenance. — Tarek M. Zayed; 18(1), 36-46 (2004).

Bridges, viaduct
Condition Assessment of the Eastbound 6th Avenue Viaduct Using Strain Gauges. — Benjamin J. Allen and Kevin L. Rens; 18(4), 205-12 (2004).

Buckling
Retrofitting a Missouri Steel Baghouse. — Donald D. Liou; 18(3), 159-64 (2004).

Budgets
Budget Allocation for Steel Bridge Paint Maintenance. — Tarek M. Zayed; 18(1), 36-46 (2004).

Building frames
Retrofitting a Missouri Steel Baghouse. — Donald D. Liou; 18(3), 159-64 (2004).

Buildings, multistory
Human Error and Reliability of Multistory Reinforced-Concrete Building Construction. — Deepthi C. Epaarachchi and Mark G. Stewart; 18(1), 12-20 (2004).

Buildings, residential
Collapse of 2000 Commonwealth Avenue: Punching Shear Case Study. — Suzanne King and Norbert J. Delatte; 18(1), 54-61 (2004).

Case reports
Collapse of 2000 Commonwealth Avenue: Punching Shear Case Study. — Suzanne King and Norbert J. Delatte; 18(1), 54-61 (2004).

Chile
Performance and Seismic Vulnerability of Masonry Housing Types Used in Chile. — M. O. Moroni, M. Astroza, and C. Acevedo; 18(3), 173-9 (2004).

Chlorides
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Collapse
Collapse of 2000 Commonwealth Avenue: Punching Shear Case Study. — Suzanne King and Norbert J. Delatte; 18(1), 54-61 (2004).
Lessons Learned on Improving Resistance of Buildings to Terrorist Attacks. — W. Gene Corley; 18(2), 68-78 (2004).
Progressive Analysis Procedure for Progressive Collapse. — S. M. Marjanishvili; 18(2), 79-85 (2004).

Colorado
Condition Assessment of the Eastbound 6th Avenue Viaduct Using Strain Gauges. — Benjamin J. Allen and Kevin L. Rens; 18(4), 205-12 (2004).

Composite materials
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).

Compressive strength
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Concrete deterioration
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Concrete pavements
Assessment of Retrofit Dowel Benefits in Cracked Portland Cement Concrete Pavements. — Jacob E. Hiller and Neeraj Buch; 18(1), 29-35 (2004).

Concrete slabs
Nondestructive Assessment of Damage in Concrete Bridge Decks. — Sarah L. Gassman and Waleed F. Tawhed; 18(4), 220-31 (2004).

Concrete, reinforced
Human Error and Reliability of Multistory Reinforced-Concrete Building Construction. — Deepthi C. Epaarachchi and Mark G. Stewart; 18(1), 12-20 (2004).

Constitutive models
Performance Simulation of Nuclear Containments for Security. — Y. L. Mo; 18(2), 107-15 (2004).

Construction
Human Error and Reliability of Multistory Reinforced-Concrete Building Construction. — Deepthi C. Epaarachchi and Mark G. Stewart; 18(1), 12-20 (2004).

Construction materials
Performance and Seismic Vulnerability of Masonry Housing Types Used in Chile. — M. O. Moroni, M. Astroza, and C. Acevedo; 18(3), 173-9 (2004).

Corrosion
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Crack propagation
Nondestructive Assessment of Damage in Concrete Bridge Decks. — Sarah L. Gassman and Waleed F. Tawhed; 18(4), 220-31 (2004).

Cracking
Assessment of Retrofit Dowel Benefits in Cracked Portland Cement Concrete Pavements. — Jacob E. Hiller and Neeraj Buch; 18(1), 29-35 (2004).
Investigation of Permeability on Indiana SR-38. — John E. Haddock and Michael Prather; 18(3), 136-41 (2004).

Curvature
Retrofitting a Missouri Steel Baghouse. — Donald D. Liou; 18(3), 159-64 (2004).

Damage assessment
Nondestructive Assessment of Damage in Concrete Bridge Decks. — Sarah L. Gassman and Waleed F. Tawhed; 18(4), 220-31 (2004).

Deflection
Contribution of Intermediate Diaphragms in Enhancing Precast Bridge Girder Performance. — Tanya Green, Nur Yazdani, and Lisa Spainhour; 18(3), 142-6 (2004).
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).
Laser-Based Instrumentation for Bridge Load Testing. — P. A. Fuchs, G. A. Washer, S. B. Chase, and M. Moore; 18(4), 213-9 (2004).

Design
Performance of Campus Parking Garages in Preventing Crime. — Chun-Hao Tseng, Josann Duane, and Fabian Hadipriono; 18(1), 21-8 (2004).
Field Performance of an Independent Full-Height Facing Reinforced Soil Wall. — Christina C. Ma and Jonathan T. H. Wu; 18(3), 165-72 (2004).

Design standards
Performance and Seismic Vulnerability of Masonry Housing Types Used in Chile. — M. O. Moroni, M. Astroza, and C. Acevedo; 18(3), 173-9 (2004).

Diaphragms
Contribution of Intermediate Diaphragms in Enhancing Precast Bridge Girder Performance. — Tanya Green, Nur Yazdani, and Lisa Spainhour; 18(3), 142-6 (2004).

Durability
Workmanship Factors Influencing Quality of Installed Parking Garage Waterproofing Membranes. — N. P. Mailvaganam and P. G. Collins; 18(3), 121-6 (2004).

Dynamic analysis
Progressive Analysis Procedure for Progressive Collapse. — S. M. Marjanishvili; 18(2), 79-85 (2004).

Earth reinforcement
Field Performance of an Independent Full-Height Facing Reinforced Soil Wall. — Christina C. Ma and Jonathan T. H. Wu; 18(3), 165-72 (2004).

Earthquake damage
Seismic Effect on Highway Bridges in Chi Chi Earthquake. — Yao T. Hsu and Chung C. Fu; 18(1), 47-53 (2004).

Electrical resistivity
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Errors
Human Error and Reliability of Multistory Reinforced-Concrete Building Construction. — Deepthi C. Epaarachchi and Mark G. Stewart; 18(1), 12-20 (2004).

Explosions
Lessons Learned on Improving Resistance of Buildings to Terrorist Attacks. — W. Gene Corley; 18(2), 68-78 (2004).
Survey of Window Retrofit Solutions for Blast Mitigation. — Lorraine H. Lin, Eve Hinman, Hollice F. Stone, and Allison M. Roberts; 18(2), 86-94 (2004).
Retrofitting Existing Masonry Buildings to Resist Explosions. — Stephen P. Ward; 18(2), 95-9 (2004).
Performance Simulation of Nuclear Containments for Security. — Y. L. Mo; 18(2), 107-15 (2004).

Explosives
Explosive Testing of Poiymer Retrofit Masonry Walls. — James S. Davidson, Jonathan R. Porter, Robert J. Dinan, Michael I. Hammons, and James D. Connell; 18(2), 100-6 (2004).

Fiber reinforced polymers
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).

Finite element method
Splitting Failures in Trapezoidal Steel Roof Cladding. — M. Mahendran and D. Mahaarachchi; 18(1), 4-11 (2004).
Nondestructive Evaluation of the I-40 Bridge over the Rio Grande River. — David V. Jáuregui and Paul J. Barr; 18(4), 195-204 (2004).

Fire
Performance Simulation of Nuclear Containments for Security. — Y. L. Mo; 18(2), 107-15 (2004).

Fuzzy sets
Safety Evaluation for Campus Parking Garage Performance Using Fuzzy Logic. — Chun-Hao Tseng, Fabian Hadipriono, Josann Duane, Patrick Maughan, and Earl W. Whitlatch; 18(3), 127-35 (2004).

Indiana
Budget Allocation for Steel Bridge Paint Maintenance. — Tarek M. Zayed; 18(1), 36-46 (2004).
Investigation of Permeability on Indiana SR-38. — John E. Haddock and Michael Prather; 18(3), 136-41 (2004).

Installation
Workmanship Factors Influencing Quality of Installed Parking Garage Waterproofing Membranes. — N. P. Mailvaganam and P. G. Collins; 18(3), 121-6 (2004).

Lasers
Laser-Based Instrumentation for Bridge Load Testing. — P. A. Fuchs, G. A. Washer, S. B. Chase, and M. Moore; 18(4), 213-9 (2004).

Lateral displacement
Retrofitting a Missouri Steel Baghouse. — Donald D. Liou; 18(3), 159-64 (2004).

Load distribution
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).
Nondestructive Evaluation of the I-40 Bridge over the Rio Grande River. — David V. Jáuregui and Paul J. Barr; 18(4), 195-204 (2004).

Load tests
Laser-Based Instrumentation for Bridge Load Testing. — P. A. Fuchs, G. A. Washer, S. B. Chase, and M. Moore; 18(4), 213-9 (2004).

Load transfer
Assessment of Retrofit Dowel Benefits in Cracked Portland Cement Concrete Pavements. — Jacob E. Hiller and Neeraj Buch; 18(1), 29-35 (2004).

Masonry
Retrofitting Existing Masonry Buildings to Resist Explosions. — Stephen P. Ward; 18(2), 95-9 (2004).
Explosive Testing of Polymer Retrofit Masonry Walls. — James S. Davidson, Jonathan R. Porter, Robert J. Dinan, Michael I. Hammons, and James D. Connell; 18(2), 100-6 (2004).
Performance and Seismic Vulnerability of Masonry Housing Types Used in Chile. — M. O. Moroni, M. Astroza, and C. Acevedo; 18(3), 173-9 (2004).

Massachusetts
Collapse of 2000 Commonwealth Avenue: Punching Shear Case Study. — Suzanne King and Norbert J. Delatte; 18(1), 54-61 (2004).

Material properties
Workmanship Factors Influencing Quality of Installed Parking Garage Waterproofing Membranes. — N. P. Mailvaganam and P. G. Collins; 18(3), 121-6 (2004).

Measurement
Field Performance of an Independent Full-Height Facing Reinforced Soil Wall. — Christina C. Ma and Jonathan T. H. Wu; 18(3), 165-72 (2004).

Membranes
Workmanship Factors Influencing Quality of Installed Parking Garage Waterproofing Membranes. — N. P. Mailvaganam and P. G. Collins; 18(3), 121-6 (2004).

New Mexico
Nondestructive Evaluation of the I-40 Bridge over the Rio Grande River. — David V. Jáuregui and Paul J. Barr; 18(4), 195-204 (2004).

New York
Lessons Learned on Improving Resistance of Buildings to Terrorist Attacks. — W. Gene Corley; 18(2), 68-78 (2004).
Progressive Analysis Procedure for Progressive Collapse. — S. M. Marjanishvili; 18(2), 79-85 (2004).

New York City
Lessons Learned on Improving Resistance of Buildings to Terrorist Attacks. — W. Gene Corley; 18(2), 68-78 (2004).

Progressive Analysis Procedure for Progressive Collapse. — S. M. Marjanishvili; 18(2), 79-85 (2004).

Nondestructive tests

Nondestructive Evaluation of the I-40 Bridge over the Rio Grande River. — David V. Jáuregui and Paul J. Barr; 18(4), 195-204 (2004).

Laser-Based Instrumentation for Bridge Load Testing. — P. A. Fuchs, G. A. Washer, S. B. Chase, and M. Moore; 18(4), 213-9 (2004).

Nondestructive Assessment of Damage in Concrete Bridge Decks. — Sarah L. Gassman and Waleed F. Tawhed; 18(4), 220-31 (2004).

Nonlinear analysis

Progressive Analysis Procedure for Progressive Collapse. — S. M. Marjanishvili; 18(2), 79-85 (2004).

Nuclear powerplants

Performance Simulation of Nuclear Containments for Security. — Y. L. Mo; 18(2), 107-15 (2004).

Oklahoma

Lessons Learned on Improving Resistance of Buildings to Terrorist Attacks. — W. Gene Corley; 18(2), 68-78 (2004).

Painting

Budget Allocation for Steel Bridge Paint Maintenance. — Tarek M. Zayed; 18(1), 36-46 (2004).

Parking facilities

Performance of Campus Parking Garages in Preventing Crime. — Chun-Hao Tseng, Josann Duane, and Fabian Hadipriono; 18(1), 21-8 (2004).

Workmanship Factors Influencing Quality of Installed Parking Garage Waterproofing Membranes. — N. P. Mailvaganam and P. G. Collins; 18(3), 121-6 (2004).

Safety Evaluation for Campus Parking Garage Performance Using Fuzzy Logic. — Chun-Hao Tseng, Fabian Hadipriono, Josann Duane, Patrick Maughan, and Earl W. Whitlatch; 18(3), 127-35 (2004).

Pavement deterioration

Investigation of Permeability on Indiana SR-38. — John E. Haddock and Michael Prather; 18(3), 136-41 (2004).

Permeability

Investigation of Permeability on Indiana SR-38. — John E. Haddock and Michael Prather; 18(3), 136-41 (2004).

Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Permits

Nondestructive Evaluation of the I-40 Bridge over the Rio Grande River. — David V. Jáuregui and Paul J. Barr; 18(4), 195-204 (2004).

Plastic hinges

Retrofitting a Missouri Steel Baghouse. — Donald D. Liou; 18(3), 159-64 (2004).

Polymers

Explosive Testing of Polymer Retrofit Masonry Walls. — James S. Davidson, Jonathan R. Porter, Robert J. Dinan, Michael I. Hammons, and James D. Connell; 18(2), 100-6 (2004).

Public safety

Performance of Campus Parking Garages in Preventing Crime. — Chun-Hao Tseng, Josann Duane, and Fabian Hadipriono; 18(1), 21-8 (2004).

Rehabilitation

Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).

Condition Assessment of the Eastbound 6th Avenue Viaduct Using Strain Gauges. — Benjamin J. Allen and Kevin L. Rens; 18(4), 205-12 (2004).

Reliability

Human Error and Reliability of Multistory Reinforced-Concrete Building Construction. — Deepthi C. Epaarachchi and Mark G. Stewart; 18(1), 12-20 (2004).

Retaining walls

Field Performance of an Independent Full-Height Facing Reinforced Soil Wall. — Christina C. Ma and Jonathan T. H. Wu; 18(3), 165-72 (2004).

Retrofitting

Assessment of Retrofit Dowel Benefits in Cracked Portland Cement Concrete Pavements. — Jacob E. Hiller and Neeraj Buch; 18(1), 29-35 (2004).

Survey of Window Retrofit Solutions for Blast Mitigation. — Lorraine H. Lin, Eve Hinman, Hollice F. Stone, and Allison M. Roberts; 18(2), 86-94 (2004).

Retrofitting Existing Masonry Buildings to Resist Explosions. — Stephen P. Ward; 18(2), 95-9 (2004).

Retrofitting a Missouri Steel Baghouse. — Donald D. Liou; 18(3), 159-64 (2004).

Roof failures

Splitting Failures in Trapezoidal Steel Roof Cladding. — M. Mahendran and D. Mahaarachchi; 18(1), 4-11 (2004).

Roofing materials

Splitting Failures in Trapezoidal Steel Roof Cladding. — M. Mahendran and D. Mahaarachchi; 18(1), 4-11 (2004).

Safety

Safety Evaluation for Campus Parking Garage Performance Using Fuzzy Logic. — Chun-Hao Tseng, Fabian Hadipriono, Josann Duane, Patrick Maughan, and Earl W. Whitlatch; 18(3), 127-35 (2004).

Security

Performance of Campus Parking Garages in Preventing Crime. — Chun-Hao Tseng, Josann Duane, and Fabian Hadipriono; 18(1), 21-8 (2004).

Performance Simulation of Nuclear Containments for Security. — Y. L. Mo; 18(2), 107-15 (2004).

Safety Evaluation for Campus Parking Garage Performance Using Fuzzy Logic. — Chun-Hao Tseng, Fabian Hadipriono, Josann Duane, Patrick Maughan, and Earl W. Whitlatch; 18(3), 127-35 (2004).

Seismic effect

Seismic Effect on Highway Bridges in Chi Chi Earthquake. — Yao T. Hsu and Chung C. Fu; 18(1), 47-53 (2004).

Seismic hazard

Performance and Seismic Vulnerability of Masonry Housing Types Used in Chile. — M. O. Moroni, M. Astroza, and C. Acevedo; 18(3), 173-9 (2004).

Shear walls

Retrofitting a Missouri Steel Baghouse. — Donald D. Liou; 18(3), 159-64 (2004).

Performance and Seismic Vulnerability of Masonry Housing Types Used in Chile. — M. O. Moroni, M. Astroza, and C. Acevedo; 18(3), 173-9 (2004).

Simulation

Performance Simulation of Nuclear Containments for Security. — Y. L. Mo; 18(2), 107-15 (2004).

Safety Evaluation for Campus Parking Garage Performance Using Fuzzy Logic. — Chun-Hao Tseng, Fabian Hadipriono, Josann Duane, Patrick Maughan, and Earl W. Whitlatch; 18(3), 127-35 (2004).

Splitting

Splitting Failures in Trapezoidal Steel Roof Cladding. — M. Mahendran and D. Mahaarachchi; 18(1), 4-11 (2004).

State government

Budget Allocation for Steel Bridge Paint Maintenance. — Tarek M. Zayed; 18(1), 36-46 (2004).

Steel structures

Retrofitting a Missouri Steel Baghouse. — Donald D. Liou; 18(3), 159-64 (2004).

Strain gauges

Condition Assessment of the Eastbound 6th Avenue Viaduct Using Strain Gauges. — Benjamin J. Allen and Kevin L. Rens; 18(4), 205-12 (2004).

Strain measurement

Nondestructive Evaluation of the I-40 Bridge over the Rio Grande River. — David V. Jáuregui and Paul J. Barr; 18(4), 195-204 (2004).

Structural analysis

Progressive Analysis Procedure for Progressive Collapse. — S. M. Marjanishvili; 18(2), 79-85 (2004).

Structural failures

Collapse of 2000 Commonwealth Avenue: Punching Shear Case Study. — Suzanne King and Norbert J. Delatte; 18(1), 54-61 (2004).

Progressive Analysis Procedure for Progressive Collapse. — S. M. Marjanishvili; 18(2), 79-85 (2004).

Structural reliability

Lessons Learned on Improving Resistance of Buildings to Terrorist Attacks. — W. Gene Corley; 18(2), 68-78 (2004).

Structural safety

Retrofitting Existing Masonry Buildings to Resist Explosions. — Stephen P. Ward; 18(2), 95-9 (2004).

Superstructures

Contribution of Intermediate Diaphragms in Enhancing Precast Bridge Girder Performance. — Tanya Green, Nur Yazdani, and Lisa Spainhour; 18(3), 142-6 (2004).

Condition Assessment of the Eastbound 6th Avenue Viaduct Using Strain Gauges. — Benjamin J. Allen and Kevin L. Rens; 18(4), 205-12 (2004).

Taiwan

Seismic Effect on Highway Bridges in Chi Chi Earthquake. — Yao T. Hsu and Chung C. Fu; 18(1), 47-53 (2004).

Temperature

Contribution of Intermediate Diaphragms in Enhancing Precast Bridge Girder Performance. — Tanya Green, Nur Yazdani, and Lisa Spainhour; 18(3), 142-6 (2004).

Temperature effects
Workmanship Factors Influencing Quality of Installed Parking Garage Waterproofing Membranes. — N. P. Mailvaganam and P. G. Collins; 18(3), 121-6 (2004).
Terrorism
Lessons Learned on Improving Resistance of Buildings to Terrorist Attacks. — W. Gene Corley; 18(2), 68-78 (2004).
Progressive Analysis Procedure for Progressive Collapse. — S. M. Marjanishvili; 18(2), 79-85 (2004).
Survey of Window Retrofit Solutions for Blast Mitigation. — Lorraine H. Lin, Eve Hinman, Hollice F. Stone, and Allison M. Roberts; 18(2), 86-94 (2004).
Retrofitting Existing Masonry Buildings to Resist Explosions. — Stephen P. Ward; 18(2), 95-9 (2004).
Explosive Testing of Polymer Retrofit Masonry Walls. — James S. Davidson, Jonathan R. Porter, Robert J. Dinan, Michael I. Hammons, and James D. Connell; 18(2), 100-6 (2004).
Tests
Explosive Testing of Polymer Retrofit Masonry Walls. — James S. Davidson, Jonathan R. Porter, Robert J. Dinan, Michael I. Hammons, and James D. Connell; 18(2), 100-6 (2004).
Universities
Performance of Campus Parking Garages in Preventing Crime. — Chun-Hao Tseng, Josann Duane, and Fabian Hadipriono; 18(1), 21-8 (2004).
Safety Evaluation for Campus Parking Garage Performance Using Fuzzy Logic. — Chun-Hao Tseng, Fabian Hadipriono, Josann Duane, Patrick Maughan, and Earl W. Whitlatch; 18(3), 127-35 (2004).
Virginia
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).
Walls
Explosive Testing of Polymer Retrofit Masonry Walls. — James S. Davidson, Jonathan R. Porter, Robert J. Dinan, Michael I. Hammons, and James D. Connell; 18(2), 100-6 (2004).
Field Performance of an Independent Full-Height Facing Reinforced Soil Wall. — Christina C. Ma and Jonathan T. H. Wu; 18(3), 165-72 (2004).
Wind loads
Splitting Failures in Trapezoidal Steel Roof Cladding. — M. Mahendran and D. Mahaarachchi; 18(1), 4-11 (2004).
Wind pressure
Retrofitting a Missouri Steel Baghouse. — Donald D. Liou; 18(3), 159-64 (2004).
Window glass
Survey of Window Retrofit Solutions for Blast Mitigation. — Lorraine H. Lin, Eve Hinman, Hollice F. Stone, and Allison M. Roberts; 18(2), 86-94 (2004).
Windows
Retrofitting Existing Masonry Buildings to Resist Explosions. — Stephen P. Ward; 18(2), 95-9 (2004).

Author Index

Acevedo, C.
Performance and Seismic Vulnerability of Masonry Housing Types Used in Chile. — M. O. Moroni, M. Astroza, and C. Acevedo; 18(3), 173-9 (2004).

Allen, Benjamin J.
Condition Assessment of the Eastbound 6th Avenue Viaduct Using Strain Gauges. — Benjamin J. Allen and Kevin L. Rens; 18(4), 205-12 (2004).

Amleh, Lamya
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Astroza, M.
Performance and Seismic Vulnerability of Masonry Housing Types Used in Chile. — M. O. Moroni, M. Astroza, and C. Acevedo; 18(3), 173-9 (2004).

Barr, Paul J.
Nondestructive Evaluation of the I-40 Bridge over the Rio Grande River. — David V. Jáuregui and Paul J. Barr; 18(4), 195-204 (2004).

Beasley, Kimball J.
Laboratory Testing for Building Failure Investigations. — Kimball J. Beasley; 18(1), 2-3 (2004).

Buch, Neeraj
Assessment of Retrofit Dowel Benefits in Cracked Portland Cement Concrete Pavements. — Jacob E. Hiller and Neeraj Buch; 18(1), 29-35 (2004).

Carper, Kenneth L.
Editor's Note. — Kenneth L. Carper; 18(1), 1 (2004).
Editor's Note. — Kenneth L. Carper; 18(2), 65 (2004).
Editor's Note. — Kenneth L. Carper; 18(3), 117 (2004).
Editor's Note. — Kenneth L. Carper; 18(4), 181-2 (2004).

Chang, Luh-Maan
Closure to "Statewide Performance Function for Steel Bridge Protection Systems" by Tarek M. Zayed, Luh-Maan Chang, and Jon D. Fricker. — Tarek M. Zayed and Luh-Maan Chang; 18(1), 63-4 (2004).

Chase, S. B.
Laser-Based Instrumentation for Bridge Load Testing. — P. A. Fuchs, G. A. Washer, S. B. Chase, and M. Moore; 18(4), 213-9 (2004).

Collins, P. G.
Workmanship Factors Influencing Quality of Installed Parking Garage Waterproofing Membranes. — N. P. Mailvaganam and P. G. Collins; 18(3), 121-6 (2004).

Connell, James D.
Explosive Testing of Polymer Retrofit Masonry Walls. — James S. Davidson, Jonathan R. Porter, Robert J. Dinan, Michael I. Hammons, and James D. Connell; 18(2), 100-6 (2004).

Corley, W. Gene
Lessons Learned on Improving Resistance of Buildings to Terrorist Attacks. — W. Gene Corley; 18(2), 68-78 (2004).

Cousins, Thomas E.
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).

Davidson, James S.
Explosive Testing of Polymer Retrofit Masonry Walls. — James S. Davidson, Jonathan R. Porter, Robert J. Dinan, Michael I. Hammons, and James D. Connell; 18(2), 100-6 (2004).

Delatte, Norbert J.
Collapse of 2000 Commonwealth Avenue: Punching Shear Case Study. — Suzanne King and Norbert J. Delatte; 18(1), 54-61 (2004).

Dinan, Robert J.
Explosive Testing of Polymer Retrofit Masonry Walls. — James S. Davidson, Jonathan R. Porter, Robert J. Dinan, Michael I. Hammons, and James D. Connell; 18(2), 100-6 (2004).

Drerup, Michael J.
Bridge Evaluations Using Nondestructive Techniques. — Michael J. Drerup; 18(4), 183-4 (2004).

Duane, Josann
Performance of Campus Parking Garages in Preventing Crime. — Chun-Hao Tseng, Josann Duane, and Fabian Hadipriono; 18(1), 21-8 (2004).
Safety Evaluation for Campus Parking Garage Performance Using Fuzzy Logic. — Chun-Hao Tseng, Fabian Hadipriono, Josann Duane, Patrick Maughan, and Earl W. Whitlatch; 18(3), 127-35 (2004).

Epaarachchi, Deepthi C.
Human Error and Reliability of Multistory Reinforced-Concrete Building Construction. — Deepthi C. Epaarachchi and Mark G. Stewart; 18(1), 12-20 (2004).

Fu, Chung C.
Seismic Effect on Highway Bridges in Chi Chi Earthquake. — Yao T. Hsu and Chung C. Fu; 18(1), 47-53 (2004).

Fuchs, P. A.
Laser-Based Instrumentation for Bridge Load Testing. — P. A. Fuchs, G. A. Washer, S. B. Chase, and M. Moore; 18(4), 213-9 (2004).

Gassman, Sarah L.
Nondestructive Assessment of Damage in Concrete Bridge Decks. — Sarah L. Gassman and Waleed F. Tawhed; 18(4), 220-31 (2004).

Green, Tanya
Contribution of Intermediate Diaphragms in Enhancing Precast Bridge Girder Performance. — Tanya Green, Nur Yazdani, and Lisa Spainhour; 18(3), 142-6 (2004).

Haddock, John E.
Investigation of Permeability on Indiana SR-38. — John E. Haddock and Michael Prather; 18(3), 136-41 (2004).

Hadipriono, Fabian
Performance of Campus Parking Garages in Preventing Crime. — Chun-Hao Tseng, Josann Duane, and Fabian Hadipriono; 18(1), 21-8 (2004).
Safety Evaluation for Campus Parking Garage Performance Using Fuzzy Logic. — Chun-Hao Tseng, Fabian Hadipriono, Josann Duane, Patrick Maughan, and Earl W. Whitlatch; 18(3), 127-35 (2004).

Hammons, Michael I.
Explosive Testing of Polymer Retrofit Masonry Walls. — James S. Davidson, Jonathan R. Porter, Robert J. Dinan, Michael I. Hammons, and James D. Connell; 18(2), 100-6 (2004).

Hiller, Jacob E.
Assessment of Retrofit Dowel Benefits in Cracked Portland Cement Concrete Pavements. — Jacob E. Hiller and Neeraj Buch; 18(1), 29-35 (2004).

Hinman, Eve
Survey of Window Retrofit Solutions for Blast Mitigation. — Lorraine H. Lin, Eve Hinman, Hollice F. Stone, and Allison M. Roberts; 18(2), 86-94 (2004).

Hsu, Yao T.
Seismic Effect on Highway Bridges in Chi Chi Earthquake. — Yao T. Hsu and Chung C. Fu; 18(1), 47-53 (2004).

Jáuregui, David V.
Nondestructive Evaluation of the I-40 Bridge over the Rio Grande River. — David V. Jáuregui and Paul J. Barr; 18(4), 195-204 (2004).

King, Suzanne
Collapse of 2000 Commonwealth Avenue: Punching Shear Case Study. — Suzanne King and Norbert J. Delatte; 18(1), 54-61 (2004).

Lesko, John J.
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).

Lin, Lorraine H.
Survey of Window Retrofit Solutions for Blast Mitigation. — Lorraine H. Lin, Eve Hinman, Hollice F. Stone, and Allison M. Roberts; 18(2), 86-94 (2004).

Liou, Donald D.
Retrofitting a Missouri Steel Baghouse. — Donald D. Liou; 18(3), 159-64 (2004).

Little, Richard G.
Protecting People in Buildings from Terrorist Attack. — Richard G. Little; 18(2), 66-7 (2004).

Ma, Christina C.
Field Performance of an Independent Full-Height Facing Reinforced Soil Wall. — Christina C. Ma and Jonathan T. H. Wu; 18(3), 165-72 (2004).

Mahaarachchi, D.
Splitting Failures in Trapezoidal Steel Roof Cladding. — M. Mahendran and D. Mahaarachchi; 18(1), 4-11 (2004).

Mahendran, M.
Splitting Failures in Trapezoidal Steel Roof Cladding. — M. Mahendran and D. Mahaarachchi; 18(1), 4-11 (2004).

Mailvaganam, N. P.
Workmanship Factors Influencing Quality of Installed Parking Garage Waterproofing Membranes. — N. P. Mailvaganam and P. G. Collins; 18(3), 121-6 (2004).

Marjanishvili, S. M.
Progressive Analysis Procedure for Progressive Collapse. — S. M. Marjanishvili; 18(2), 79-85 (2004).

Maughan, Patrick
Safety Evaluation for Campus Parking Garage Performance Using Fuzzy Logic. — Chun-Hao Tseng, Fabian Hadipriono, Josann Duane, Patrick Maughan, and Earl W. Whitlatch; 18(3), 127-35 (2004).

Minocha, Vijay K.
Discussion of "Statewide Performance Function for Steel Bridge Protection Systems" by Tarek M. Zayed, Luh-Maan Chang, and Jon D. Fricker. — Vijay K. Minocha; 18(1), 62-3 (2004).

Mirza, M. Saeed
Corrosion Response of a Decommissioned Deteriorated Bridge Deck. — Lamya Amleh and M. Saeed Mirza; 18(4), 185-94 (2004).

Mo, Y. L.
Performance Simulation of Nuclear Containments for Security. — Y. L. Mo; 18(2), 107-15 (2004).

Moore, M.
Laser-Based Instrumentation for Bridge Load Testing. — P. A. Fuchs, G. A. Washer, S. B. Chase, and M. Moore; 18(4), 213-9 (2004).

Moroni, M. O.
Performance and Seismic Vulnerability of Masonry Housing Types Used in Chile. — M. O. Moroni, M. Astroza, and C. Acevedo; 18(3), 173-9 (2004).

Neely, W. Douglas
Evaluation of In-Service Performance of Tom's Creek Bridge Fiber-Reinforced Polymer Superstructure. — W. Douglas Neely, Thomas E. Cousins, and John J. Lesko; 18(3), 147-58 (2004).

Porter, Jonathan R.
Explosive Testing of Polymer Retrofit Masonry Walls. — James S. Davidson, Jonathan R. Porter, Robert J. Dinan, Michael I. Hammons, and James D. Connell; 18(2), 100-6 (2004).

Prather, Michael
Investigation of Permeability on Indiana SR-38. — John E. Haddock and Michael Prather; 18(3), 136-41 (2004).

Rens, Kevin L.
Technical Council on Forensic Engineering Survey of Member Needs. — Kevin L. Rens; 18(3), 118-20 (2004).
Condition Assessment of the Eastbound 6th Avenue Viaduct Using Strain Gauges. — Benjamin J. Allen and Kevin L. Rens; 18(4), 205-12 (2004).

Roberts, Allison M.
Survey of Window Retrofit Solutions for Blast Mitigation. — Lorraine H. Lin, Eve Hinman, Hollice F. Stone, and Allison M. Roberts; 18(2), 86-94 (2004).

Spainhour, Lisa
Contribution of Intermediate Diaphragms in Enhancing Precast Bridge Girder Performance. — Tanya Green, Nur Yazdani, and Lisa Spainhour; 18(3), 142-6 (2004).

Stewart, Mark G.
Human Error and Reliability of Multistory Reinforced-Concrete Building Construction. — Deepthi C. Epaarachchi and Mark G. Stewart; 18(1), 12-20 (2004).

Stone, Hollice F.
Survey of Window Retrofit Solutions for Blast Mitigation. — Lorraine H. Lin, Eve Hinman, Hollice F. Stone, and Allison M. Roberts; 18(2), 86-94 (2004).

Tawhed, Waleed F.
Nondestructive Assessment of Damage in Concrete Bridge Decks. — Sarah L. Gassman and Waleed F. Tawhed; 18(4), 220-31 (2004).

Tseng, Chun-Hao
Performance of Campus Parking Garages in Preventing Crime. — Chun-Hao Tseng, Josann Duane, and Fabian Hadipriono; 18(1), 21-8 (2004).
Safety Evaluation for Campus Parking Garage Performance Using Fuzzy Logic. — Chun-Hao Tseng, Fabian Hadipriono, Josann Duane, Patrick Maughan, and Earl W. Whitlatch; 18(3), 127-35 (2004).

Ward, Stephen P.
Retrofitting Existing Masonry Buildings to Resist Explosions. — Stephen P. Ward; 18(2), 95-9 (2004).

Washer, G. A.
Laser-Based Instrumentation for Bridge Load Testing. — P. A. Fuchs, G. A. Washer, S. B. Chase, and M. Moore; 18(4), 213-9 (2004).

Whitlatch, Earl W.
Safety Evaluation for Campus Parking Garage Performance Using Fuzzy Logic. — Chun-Hao Tseng, Fabian Hadipriono, Josann Duane, Patrick Maughan, and Earl W. Whitlatch; 18(3), 127-35 (2004).

Wu, Jonathan T. H.
Field Performance of an Independent Full-Height Facing Reinforced Soil Wall. — Christina C. Ma and Jonathan T. H. Wu; 18(3), 165-72 (2004).

Yazdani, Nur
Contribution of Intermediate Diaphragms in Enhancing Precast Bridge Girder Performance. — Tanya Green, Nur Yazdani, and Lisa Spainhour; 18(3), 142-6 (2004).

Zayed, Tarek M.
Budget Allocation for Steel Bridge Paint Maintenance. — Tarek M. Zayed; 18(1), 36-46 (2004).
Closure to "Statewide Performance Function for Steel Bridge Protection Systems" by Tarek M. Zayed, Luh-Maan Chang, and Jon D. Fricker. — Tarek M. Zayed and Luh-Maan Chang; 18(1), 63-4 (2004).